# OPEN FIRST!!



1131 VIA CALLEJON, SAN CLEMENTE, CA 92673

(C) 2004 Energy Suspension. All rights reserved.

May not be reproduced, in any form, or by any means, without the written consent of Energy Suspension.

# **Parts List for** Master set # 7-18106

#### Parts list:

Energy Suspension recommends that you read over all the installation instructions and check all P/N's and quantities in the parts list before you start. Call customer service at 949-361-3935 if the parts in your kit do not match this parts list.

### Front strut rod bushing set: 7.7105

- 2 7119 inner bushing.
- 4 7120 outer bushing.
- 2 15.10.325.39 sleeve(1.000" x .563" x 2.745").
- 4 9.11108 grease.
- 1 17432 installation instructions.

#### Front control arm bushing set: 7.3114

- 2 15.10.517.39 Sleeve (0.750"x0.563"x2.480")
- 2 3429 Bushing with built on thrust washer
- 2 3252 Bushing without built on thrust washer
- 1 9.11101 grease.
- 1 17394 Instruction sheet

#### Front sway bar bushing set: 7.5121

- 2 5740 24mm bar bushing
- 2 8190 Upper endlink bushing
- 2 8191 Lower endlink bushing
- 1 9.11108 grease

#### Front sway bar bushing set: 7.5123

- 2 5750 25mm bar bushing
- 2 8190 Upper endlink bushing
- 2 8191 Lower endlink bushing
- 1 9.11108 grease
- \*(Depending or your bar size, you will not use 2 sway bar bushings.)

#### Rear control arm/suspension set: 7.3115

- 4 8310 Control arm bushing (1.720" OAL)
- 4 15.10.155.39 Sleeve (0.750"x0.480"x1.760")
- 12 8309 Various arms bushing (1.420" OAL)
- 12 15.10.518.39 Sleeve (0.875"x0.500"x1.565")
- 4 9.11101 yellow grease tubs
- 1 17395 Instruction sheet

# Rear sway bar bushing set: 7.5122

- 2 5748 15mm sway bar bushing
- 6 8147 Bar/frame endlink bushing
- 2 8148 Upper frame endlink bushing
- 1 9.11108 grease
- 1 17396 Instruction sheet

#### Rear subframe inserts set: 7.1113

- 2 1181 Front position inserts
- 2 1182 Rear position inserts
- 4 15.03.37.39 Washer (1.750"x0.562"x0.125")
- 1 17409 Instruction sheet

# Rack and pinion bushing set: 7.10104

- 1 10034 Drivers side bushing
- 1 10035 Passenger side bushing



012104 NT NISSAN 240SX

Updated 9/DEC/04 BRH