MSD GM LS Engine Coil Brackets For LS1/LS6 Engines, PN 8215 For LS2/LS7 Engines, PN 8216

ONLINE PRODUCT REGISTRATION: Register your MSD product online. Registering your product will help if there is ever a warranty issue with your product and helps the MSD R&D team create new products that you ask for! Go to www.msdperformance.com/registration.

Parts Included:

2 - GM LS Engine Coil Brackets Mounting Hardware (16 bolts)

This MSD Coil Bracket has been designed to dress up the top of GM's LS engines. The 8215 Coil Bracket will work on stock coils for LS1 and LS6 engines or with MSD coil PN 8285. This bracket will NOT work with MSD coil PN 8286 or MSD coil PN 8287.

The 8216 Coil Bracket will work on stock coils for LS2 and LS7engines or with MSD coil PN 8287. This bracket will NOT work with MSD coil PN 8285 or MSD coil PN 8286. Please ensure the selected bracket part number matches your engine!

PN 82858 - Coil Kits for LS1/LS6 engines PN 82878 - Coil Kits for LS2/LS7 engines

The brackets are a direct replacement for the stock coil mounting system that enhances the late model look – especially when paired with MSD's Multiple Spark Coils for the LS.

Note: Always use the supplied hardware when installing MSD Coils or Coil Brackets.

- 1. Disconnect harnesses from the coils.
- 2. Remove coils from existing brackets
- 3. Remove existing brackets from top of engine.
- 4. Install the MSD Coil Brackets using the supplied hardware.
- 5. Mount coils on MSD Coil Brackets.
- 6. Reconnect wiring harnesses to coils.

TECH NOTES

Service

In case of malfunction, this MSD component will be repaired free of charge according to the terms of the warranty. When returning MSD components for warranty service, **Proof of Purchase** must be supplied for verification. After the warranty period has expired, repair service is based on a minimum and maximum fee.

All returns must have a Return Material Authorization (RMA) number issued to them before being returned. To obtain an RMA number please contact MSD Customer Service at 1 (888) MSD-7859 or visit our website at www.msdignition.com/rma to automatically obtain a number and shipping information.

When returning the unit for repair, leave all wires at the length in which you have them installed. Be sure to include a detailed account of any problems experienced, and what components and accessories are installed on the vehicle. The repaired unit will be returned as soon as possible using Ground shipping methods (ground shipping is covered by warranty). For more information, call MSD Ignition at (915) 855-7123. MSD technicians are available from 7:00 a.m. to 5:00 p.m. Monday - Friday (mountain time).

Limited Warranty

MSD IGNITION warrants this product to be free from defects in material and workmanship under its intended normal use*, when properly installed and purchased from an authorized MSD dealer, for a period of one year from the date of the original purchase. This warranty is void for any products purchased through auction websites. If found to be defective as mentioned above, it will be repaired or replaced at the option of MSD Ignition. Any item that is covered under this warranty will be returned free of charge using Ground shipping methods.

This shall constitute the sole remedy of the purchaser and the sole liability of MSD Ignition. To the extent permitted by law, the foregoing is exclusive and in lieu of all other warranties or representation whether expressed or implied, including any implied warranty of merchantability or fitness. In no event shall MSD Ignition or its suppliers be liable for special or consequential damages.

*Intended normal use means that this item is being used as was originally intended and for the original application as sold by MSD Ignition. Any modifications to this item or if it is used on an application other than what MSD Ignition markets the product, the warranty will be void. It is the sole responsibility of the customer to determine that this item will work for the application they are intending. MSD Ignition will accept no liability for custom applications.