## Installation Instructions for set # 4-5178

- 1. Remove sway bar brackets from vehicle undercarriage.
- 2. Remove sway bar bushings from front sway bar.
- 3. Apply supplied grease to I.D. of polyurethane bushings.
- 4. Install polyurethane bushings onto sway bar as shown.
- 5. Install sway bar brackets and torque fasteners to factory specs.

© 2002 Energy Suspension. All rights reserved.

May not be reproduced, in any form, or by any means, without the written consent of Energy Suspension.

17321

6-7-00 jl

Updated 8/MAY/02 BRH




1131 VIA CALLEJON, SAN CLEMENTE, CA 92673

It is recommended that a factory service manual be purchased prior to performing any work on your car or truck.



Front of vehicle



## Installation Instructions for set # 4-5178

- 1. Remove sway bar brackets from vehicle undercarriage.
- 2. Remove sway bar bushings from front sway bar.
- 3. Apply supplied grease to I.D. of polyurethane bushings.
- 4. Install polyurethane bushings onto sway bar as shown.
- 5. Install sway bar brackets and torque fasteners to factory specs.

© 2002 Energy Suspension. All rights reserved. May not be reproduced, in any form, or by any means, without the written consent of Energy Suspension.

17321

6-7-00 jl

Jpdated 8/MAY/02 BRH




1131 VIA CALLEJON, SAN CLEMENTE, CA 92673

It is recommended that a factory service manual be purchased prior to performing any work on your car or truck.



Front of vehicle



## Installation Instructions for set # 4-5178

- 1. Remove sway bar brackets from vehicle undercarriage.
- 2. Remove sway bar bushings from front sway bar.
- 3. Apply supplied grease to I.D. of polyurethane bushings.
- 4. Install polyurethane bushings onto sway bar as shown.
- 5. Install sway bar brackets and torque fasteners to factory specs.




1131 VIA CALLEJON, SAN CLEMENTE, CA 92673

It is recommended that a factory service manual be purchased prior to performing any work on your car or truck.



Front of vehicle



© 2002 Energy Suspension. All rights reserved.

May not be reproduced, in any form, or by any means, without the written consent of Energy Suspension.

1732

Jpdated 8/MAY/02 BRH